

41 21 09 73 43 27 WELL COMPLETION REPORT

P936

This report is to be completed by well driller and submitted to Health Department, together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality, before certificate of construction compliance is issued.

Well construction to be in accordance with Bulletin SD-62
"RULES & REGULATIONS RELATING TO INDIVIDUAL WATER SUPPLIES"

700 S

LOCATION: MUNICIPALITY TOWN OF CARMEL SECTION A. BLOCK 7 LOT 33.34

WELL OWNER: HONKOLA BUILDERS, INC., Hillside Terrace, Mahopac, New York
Name Street Address City and Town

WELL DRILLER: MILL DRILLING, INC., Putnam Avenue, Brewster, New York
Name Street Address City and Town

CASING DETAILS		YIELD TEST		WATER LEVEL		SCREEN DETAILS	
Length:	49	Feet	Bailed	(measure from land surface)		Feet	Make:
			X Pumped 2	Hours Static:	35		
Diameter:	6	Inches	Yield:	12	When Bailed	160	Slot
			G.P.M.	or Pumped	Feet	Length	Ft. Size
Kind:	Steel					Diameter	In.

TOTAL DEPTH OF WELL 160 FEET

WELL LOG

Depth From Ground Surface	Give description of formations penetrated, such as: peat, silt, sand, gravel, clay, hardpan, shale, sandstone, granite, etc. Include size of gravel (diameter) and sand (fine, medium, coarse), color of material, structure (Loose, packed, cemented, soft, hard). For example: 0 ft. to 27 ft. fine, packed, yellow sand; 27 ft. to 134 ft. gray granite.
0 Ft. to 42 Ft.	Hardpan.
42 Ft. to 45 Ft.	Weathered ledge.
45 Ft. to 160 Ft.	Hard gray granite.
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	

Date Well Was Completed May 21, 1971 Date of Report May 28, 1971
Well Driller Robert M. Mill Pres.
Signature
MILL DRILLING, INC.